





WITH SHAFT IN DOWN POSITION, CUTTER
MUST BE FLUSH WITH END OF GUIDE
SKIRT.

FILE C:\Exploded\HS310-6C.DWG

CHG. LTR.	DATE	FILE NO.	SIGNED	DATE	OLYMPIC FASTENING SYSTEMS DIVISION OF GESIPA FASTENERS USA, INC P.O. BOX 5068 TRENTON, NEW JERSEY 08638	
A	3/19/99	RELEASE	APPROVED	11/26/02		HS 310-6C
B	11/26/02	19055	CHECKED	11/26/02		
			DRAWN			
			G.W.D.	3/19/99		
					Rivet Head Shaver	



FILE: C:\EXPLODED\8037.DWG

CHG. LTR.	DATE	FILE NO.	SIGNED	DATE
A	3/19/99	RELEASE	APPROVED	
B	11/26/02	19055	<i>[Signature]</i>	11/26/02
			CHECKED	
			<i>[Signature]</i>	11/26/02
			DRAWN	
			G.W.D.	3/19/99

OLYMPIC FASTENING SYSTEMS
 DIVISION OF GESIPA FASTENERS USA, INC
 P.O. BOX 5068
 TRENTON, NEW JERSEY 08638



Shaft Sub-Assembly

8037