


NOTES:

- 1 APPLY ANTI-SEIZE LUBRICANT P/N: 508183 TO OUTSIDE OF PULLER
- 2 APPLY VIBRA-TITE P/N: 505125 TO SET SCREW THREADS PER MFR'S INSTRUCTIONS.
- 3 APPLY WARNING STICKER P/N: 590273 TO ANVIL HOLDER. DO NOT PERMIT STICKER TO OVERLAP ONTO ANVIL.

REV	DESCRIPTION	DET	DATE
A	RELEASE	SMA	07/29/15



501736	1	SSCR SOC CON #08-32 X .19	6
590273	1	STICKER, WARNING, MOVING PARTS	5
130970	1	HOLDER, ANVIL, CUT, BTT14	4
502017	4	SSCR SOC FLT #10-32X .19 LW	3
129969	1	ANVIL, CUT, -16 BT	2
130968	1	PULLER, CUT, BTT14, -16 BT	1
PART NO.	QTY	DESCRIPTION	ITEM

IDENTIFICATION PER SPEC 42-311: ★ PERMANENT		HUCK INTERNATIONAL, INC., I.S.D 1 CORPORATE DR KINGSTON, NEW YORK 12401	
ITAR/ECCN: EAR99		NOSE, CUT, -16BT BTT14 TOOL	
SCH B#: 8467.99.0190		FINAL ASSY: -	
HTS: 8467.99.0190		ENG: SMA	CK: DATE: 07/29/15 SCALE: 1:1
		B	99-7810CX