



- NOTES:
- 1 APPLY ANTI-SEIZE LUBRICANT P/N: 508183 TO OUTSIDE OF PULLER AND INSIDE OF ANVIL.
 - 2 APPLY VIBRA-TITE P/N: 505125 TO SET SCREW THREADS PER MFR'S INSTRUCTIONS.
 - 3 APPLY WARNING STICKER P/N: 590273 TO ANVIL HOLDER. DO NOT PERMIT STICKER TO OVERLAP ONTO ANVIL

REV	DESCRIPTION	DET	DATE
A	RELEASE	HKS	9/8/11



590273	1	WARNING STICKER	7
501736	1	SET SCREW, #8-32 X 3/16	6
128968	1	ANVIL HOLDER, COLLAR SPLITTER	5
501920	3	SET SCREW, #10-32 X 3/16	4
502017	4	SET SCREW, #10-32 X 3/16	3
130009	1	ANVIL, COLLAR SPLITTER	2
130010	1	PULLER, COLLAR SPLITTER	1
PART NO.	QTY	DESCRIPTION	ITEM
IDENTIFICATION PER SPEC 42-311: ★ PERMANENT		HUCK INTERNATIONAL, INC., I.S.D 1 CORPORATE DR KINGSTON, NEW YORK 12401	
ITAR/ECCN: EAR99		ASSY, BT-20(5/8") MBT-16(16MM) COLLAR SPLITTER BTT35LS TOOL	
SCH B#: 8467.99.0190		FINAL ASSY: -	
HTS: 8467.99.0190		ENG: TRK CK:	DATE: 9/8/11 SCALE: 1:1
		B	99-7821CX