


NOTES:

- 1 APPLY ANTI-SEIZE LUBRICANT P/N: 505565 TO OUTSIDE OF PULLER.
- 2 APPLY VIBRA-TITE P/N: 505125 TO SET SCREW THREADS PER MFR'S INSTRUCTIONS.
- 3 APPLY WARNING STICKER P/N: 590273 TO ANVIL HOLDER. DO NOT PERMIT STICKER TO OVERLAP ONTO ANVIL

REV	DESCRIPTION	DET	DATE
A	RELEASE	HKS	09/08/11
B	ADDED 501920 SETSCREWS	SMA	01/08/15



(B)	50 1920	3	SSCR SOC CUP #10-32X .19 LW	7
	590 273	1	STICKER, WARNING, MOVING PARTS	6
	50 1736	1	SSCR SOC CON #08-32 X .19	5
	1290 52	1	HOLDER, ANVIL, CUT, BTT35LS	4
	50 1817	4	SSCR SOC FLT #10-32 X .25	3
	1300 11	1	ANVIL, CUT, BTT35LS, 20MM BT	2
	1300 12	1	PULLER, CUT, BTT35LS, 20MM BT	1
PART NO.		QTY	DESCRIPTION	ITEM
IDENTIFICATION PER SPEC 42-311: ★ PERMANENT			HUCK INTERNATIONAL, INC., I.S.D 1 CORPORATE DR KINGSTON, NEW YORK 12401	
ITAR/ECCN: EAR99			ASSY, MBT-20(20MM) & BT-24(3/4") COLLAR SPLITTER BTT35LS TOOL	
SCH B#: 8467.99.0190			FINAL ASSY: -	
HTS: 8467.99.0190			ENG: TRK	CK: DATE: 9/8/11 SCALE: 1:1
			B	99-7822CX