



REV	DESCRIPTION	DET	DATE
A	RELEASE	HKS	9/8/11

- NOTES:
- 1 APPLY ANTI-SEIZE LUBRICANT P/N: 505565 TO OUTSIDE OF PULLER.
 - 2 APPLY VIBRA-TITE P/N: 505125 TO SET SCREW THREADS PER MFR'S INSTRUCTIONS.
 - 3 APPLY WARNING STICKER P/N: 590273 TO ANVIL HOLDER. DO NOT PERMIT STICKER TO OVERLAP ONTO ANVIL.



590 273	1	WARNING STICKER	7
50 1736	1	C.P.S.S. #8-32 X 3/16	6
50 1920	3	C.P.S.S. #10-32 X 3/16	5
1290 43	1	ANVIL HOLDER, COLLAR SPLITTER	4
50 20 17	4	F.P.S.S. #10-32 X 3/16	3
1300 13	1	ANVIL, COLLAR SPLITTER	2
1300 14	1	PULLER, COLLAR SPLITTER	1
PART NO.	QTY	DESCRIPTION	ITEM
IDENTIFICATION PER SPEC 42-311: ★ PERMANENT		HUCK INTERNATIONAL, INC., I.S.D 1 CORPORATE DR KINGSTON, NEW YORK 12401	
ITAR/ECCN: EAR99		ASSY, MBT-14 (14MM) COLLAR SPLITTER BTT35LS TOOL	
SCH B#: 8467.99.0190		FINAL ASSY: -	
HTS: 8467.99.0190		ENG: TRK CK: DATE: 9/8/11 SCALE: 1:1	
		B	99-7824CX