


NOTES:

- 1 APPLY ANTI-SEIZE LUBRICANT P/N: 508183 TO OUTSIDE OF PULLER.
- 2 APPLY VIBRA-TITE P/N: 505125 TO SET SCREW THREADS PER MFR'S INSTRUCTIONS.
- 3 APPLY WARNING STICKER P/N: 590273 TO ANVIL HOLDER. DO NOT PERMIT STICKER TO OVERLAP ONTO ANVIL

REV	DESCRIPTION	DET	DATE
A	RELEASE	HKS	9/8/11
B	REMOVED NOTE 4 (LOCTITE 242)	HKS	7/13/15



590 273	1	WARNING STICKER	8
50 1781	4	SET SCREW #8-32 X 3/16	7
1290 98	1	LOCK NUT	6
1290 22	1	ADAPTER ASSEMBLY	5
50 1027	1	RETAINING RING	4
129867	1	ANVIL HOLDER, COLLAR SPLITTER	3
129975	1	ANVIL, COLLAR SPLITTER	2
1300 18	1	PULLER, COLLAR SPLITTER	1
PART NO.	QTY	DESCRIPTION	ITEM

IDENTIFICATION PER SPEC 42-311: ★ PERMANENT		HUCK INTERNATIONAL, INC., I.S.D 1 CORPORATE DR KINGSTON, NEW YORK 12401	
ITAR/ECCN: EAR99		ASSY, MBT-12(12MM) COLLAR SPLITTER 3585 TOOL	
SCH B#: 8467.99.0190		FINAL ASSY: -	
HTS: 8467.99.0190		ENG: TRK CK: DATE: 9/8/11 SCALE: 1:1	
		B	99-7830CX