



NOTES:

- 1 APPLY ANTI-SEIZE LUBRICANT P/N: 508183 TO OUTSIDE OF PULLER AND INSIDE OF ANVIL
- 2 APPLY LOCTITE 242 P/N: 505016 TO THESE THREADED JOINTS PER MFR'S INSTRUCTIONS.
- 3 APPLY VIBRA-TITE P/N: 505125 TO SET SCREW THREADS PER MFR'S INSTRUCTIONS.
- D 4 APPLY WARNING STICKER P/N: 590273 TO ANVIL HOLDER. DO NOT PERMIT STICKER TO OVERLAP ONTO ANVIL.



SECTION A - A

501736	1	SET SCREW	5
501920	3	SET SCREW	4
128389	1	PULLER	3
128376	1	ANVIL HOLDER	2
128379	1	ANVIL ASSEMBLY	1
PART NO.	QTY	DESCRIPTION	ITEM

HUCK INTERNATIONAL, INC., I.S.D.
1 CORPORATE DR., P.O. BOX 2270
KINGSTON, NEW YORK 12401

NOSE ASSEMBLY 5/8" (16MM) BOBTAIL
BTT35 TOOL

DET: TRK CK: DATE: 3/23/07 SCALE: 1:1

FOC. FAC. B 99-7851

REV	DESCRIPTION	DATE
B	CHANGED QTY OF 501736 500648 WAS 501691	3/29/07
C	ADDED NOTE 3; 501920 WAS 500648	9/9/07
D	ADDED WARNING STICKER P/N:590273	7/28/08