



- NOTES:
- 1 APPLY ANTI-SEIZE LUBRICANT P/N: 508183 TO OUTSIDE OF PULLER.
 - 2 APPLY VIBRA-TITE P/N: 505125 TO SET SCREW THREADS PER MFR'S INSTRUCTIONS.
 - 3 APPLY WARNING STICKER P/N: 590273 TO ANVIL HOLDER. DO NOT PERMIT STICKER TO OVERLAP ONTO ANVIL

REV	DESCRIPTION	DET	DATE
A	RELEASE	HKS	9/8/11



590273	1	WARNING STICKER	6
501736	1	C.P.S.S. #8-32 X .19	5
129127	1	ANVIL HOLDER, COLLAR SPLITTER	4
501818	4	F.P.S.S. 1/4-28 X .25	3
129973	1	ANVIL, COLLAR SPLITTER	2
129974	1	PULLER, COLLAR SPLITTER	1
PART NO.	QTY	DESCRIPTION	ITEM

IDENTIFICATION PER SPEC 42-311: ★ PERMANENT		HUCK INTERNATIONAL, INC., I.S.D 1 CORPORATE DR KINGSTON, NEW YORK 12401	
ITAR/ECCN: EAR99		ASSY, BT-28(7/8")COLLAR SPLITTER BTT57 TOOL	
SCH B#: 8467.99.0190		FINAL ASSY: -	
HTS: 8467.99.0190		ENG: TRK CK: DATE: 9/8/11 SCALE: 1:1	
		B	99-7853CX