



NOTES:

- 1 APPLY ANTI-SEIZE LUBRICANT P/N: 508183 TO OUTSIDE OF PULLER AND INSIDE OF ANVIL
- 2 APPLY LOCTITE 242 P/N: 505016 TO THESE THREADED JOINTS PER MFR'S INSTRUCTIONS.
- 3 APPLY VIBRA-TITE P/N: 505125 TO SET SCREW THREADS PER MFR'S INSTRUCTIONS.
- 4 APPLY WARNING STICKER P/N: 590273 TO ANVIL HOLDER. DO NOT PERMIT STICKER TO OVERLAP ONTO ANVIL.



SECTION A-A

|          |     |                |      |
|----------|-----|----------------|------|
| 501736   | 1   | SET SCREW      | 5    |
| 501920   | 3   | SET SCREW      | 4    |
| 129002   | 1   | PULLER         | 3    |
| 129003   | 1   | ANVIL HOLDER   | 2    |
| 129004   | 1   | ANVIL ASSEMBLY | 1    |
| PART NO. | QTY | DESCRIPTION    | ITEM |

HUCK INTERNATIONAL, INC., I.S.D.  
1 CORPORATE DR., P.O. BOX 2270  
KINGSTON, NEW YORK 12401

NOSE ASSEMBLY 1/2" BOBTAIL  
BTT25 TOOL

DET: HKS CK: DATE: 9/15/08 SCALE: 1:1

FOC. FAC. B 99-7855