


PRH850-540 ADAPTOR

Consists of Two Assemblies Shown Below. Assemblies may be purchased complete or as individual components for replacement

PRH850-40 Draw Bolt Assembly



NOTE:

APPLY LOCTITE 290 EVENLY AROUND THREADED AREA OF PRH850-17 DRAW BOLT SCREW. INTERNAL DIAMETERS AND FACE SURFACE OF PRH850-45 DRAW BOLT ADAPTOR & FACE SURFACE OF PRH850-18 DRAW BOLT TO BE FREE OF LOCTITE. PRH850-45 DRAW BOLT ADAPTOR MUST TURN FREELY AFTER LOCTITE HAS CURED.

PRH850-43 Corner Head Adaptor

