


NOTES:

1- DRAWBOLT MUST THREAD INTO COLLET BY HAND.



FILE: C:\exploded\8012-7.dwg

CHG. LTR.	DATE	FILE NO.	SIGNED	DATE	OLYMPIC FASTENING SYSTEMS DIVISION OF GESIPA FASTENERS USA, INC  P.O. BOX 5068 TRENTON, NEW JERSEY 08638	
A	4/30/98	RELEASE	APPROVED		Drawbolt Sub-Assembly	8012-7
B	10/28/02	19052				
			CHECKED			
			DRAWN			
			G.W.D.	4/30/98		