



NOTE:

- 1 APPLY ANTI-SIEZE LUBRICANT P/N 508183 TO OUTSIDE OF PULLER
INSIDE OF ANVIL
- 2 APPLY LOCTITE 243 P/N 508183 TO THESE THREADS
- 3 APPLY VIBRA-TITE P/N 505125 TO SET SCREWS
- 4 APPLY WARNING STICKER P/N 590273 TO ANVIL HOLDER. DO NOT
PERMIT STICKER TO OVERLAP ONTO ANVIL

REV	DESCRIPTION	DET	DATE
A	RELEASE	SMA	12/12/17
B	(.22) WAS (.19), (5.81) WAS (5.84)	SMA	01/04/18



SECTION A-A

501736	2	SSCR SOC CON #08-32 X .19	5
501920	3	SSCR SOC CUP #10-32X .19	4
128389	1	PULLER, BTT35, 16MM & -20 BT	3
128376	1	HOLDER, ANVIL	2
128379XA	1	ANVIL ASM, BTT35, 16MM &-20 LS	1
PART NO.	QTY	DESCRIPTION	ITEM
IDENTIFICATION PER SPEC 42-311: ★ PERMANENT		HUCK INTERNATIONAL, INC., I.S.D 1 CORPORATE DR KINGSTON, NEW YORK 12401	
ITAR/ECCN: EAR99		NOSE, 16MM & -20 BT LS BTT35 TOOL	
SCH B#: 8467.99.0190		FINAL ASSY: -	
HTS: 8467.99.0190		ENG: SMA CK: DATE: 10/30/17 SCALE: 1:1	
		B	99BT-M16-IRA0-XA